Level-13, AJ Heights, Cha-72/1/d North Badda, Pragati Sarani Dhaka-1212, Bangladesh PABX: +880 2 41081863-6

⊣www.rsc-bd.ora⊢

Date: 27/10/2022

Subject: RMG Sustainability Council (RSC) Structural Safety Assessment for KM

Nobely Garments Ltd (23244)

For the attention of Factory Owner/Manager, Lead Brand, Responsible Participating Companies &

Union Colleagues

We are writing to inform you of the RMG Sustainability Council (RSC) Structural Safety Assessment

for the below factory.

Factory Name: KM Nobely Garments Ltd (Account ID: 23244)

Address: Zorun, Konabari Gazipur-1702

The RSC conducted an initial structural assessment at this facility on 21/12/2020. The RSC also

conducted follow-up structural inspections last on 12/10/2022.

The factory has completed remediation on all structural issues identified in the RSC initial and RSC

follow-up structural inspection reports for this factory. Any color category associated with this

factory is no longer valid, and the RSC is satisfied that general compliance with our structural safety

standard is achieved.

Please note that this clearance is given based on the inspections conducted by the RSC and does not

cover any modifications, extensions etc. which have taken place after the initial inspection unless

specifically verified by the RSC. The factory must ensure the ongoing compliance with loading plans

and maintenance to ensure the integrity of the building. The RSC reserves the right to add further

structural findings in the future.

This letter is a reference to structural findings only. It does not reference fire and electrical findings.

Sincerely,

George Bernard Faller

Chief Safety Officer

RMG Sustainability Council (RSC)